MATERIAL SAFETY DATA SHEET

FOR COATINGS, RESINS AND RELATED MATERIALS

DATE OF PREP.

10 - 81

(Approved by U.S. Department of Labor "Essentially Similar" to Form OSHA-20)

Section I

MANUFACTURER'S NAME

BOSTIK WEST, DIVISION OF EMHART CORPORATION

STREET ADDRESS

20846 S. NORMANDIE AVE. CITY, STATE, AND ZIP CODE TORRANCE, CA.

90502

EMERGENCY TELEPHONE NO. (213) 320-6800

BOSTIK

PRODUCT CLASS

TRADE NAME

MANUFACTURERS CODE IDENTIFICATION

Catalyst for 443-3-Series; 3 parts base to 1 part X-304.

453-1000 Series; 4 parts base to 1 part X-304.

463-3-Series; 4 parts base to 1 part X-304.

Section II — HAZARD	OUS INGREDIE	NTS
---------------------	--------------	-----

COCIONII — MAZANDOGG (NGMEDIENTO					
INGREDIENT X-304 EPOXY CATALYST*	CAS NO.	PERCENT (Wt.)	TLV PPM mg/M³	LEL	VAPOR PRESSURE
Methyl Ethyl Ketone	78-93-3	25-30	200	1.8	70
Butyl Alcohol	71-36-3	20-25	100050	1.7	- 4
Butyl Acetate	123-86-4	20-25	150	1.7	8
Butyl Cellosolve	111-76-2	10-15	50	1.1	1
Toluene	108-88-3	5-10	200 100	1.2	22
*X-304 may also contain a minor amount of diethylene triamine(DETA) ACGIH, TWA	111-40-0		1.0		

Section III - PHYSICAL DATA

BOILING RANGE

176-340° F.

VAPOR DENSITY

X HEAVIER

LIGHTER, THAN AIR

FASTER X SLOWER, THAN ETHER

PERCENT VOLATILE BY VOLUME

75%

WEIGHT PER

7.1 1bs.

Section IV — FIRE AND EXPLOSION HAZARD DATA

DOTCATEGORYed Label, Flammable

23°

Tag Closed Cup

1.1

EXTINGUISHING MEDIA

Exclude air-Use foam, CO2, steam, water fog, dry chemicals. Do not use water.

UNUSUAL FIRE AND EXPLOSION HAZARDS

Vapor forms explosive mixture with air between

upper and lower explosion limits.

SPECIAL FIRE FIGHTING PROCEDURES

Do not use water, exclude air, use water spray to cool fire exposed surfaces and to protect personnel:

Section V — HEALTH HAZARD DATA
EMERGENCY and first aid procedures: Skin Exposure: Wash affected area with soap and water. Eye Exposure: Flush with water for at least 15 minutes, consult physician. Ingestion: Consult physician immediately.
<u>Inhalation</u> : Remove victim to fresh air., consult physician.
Section VI — REACTIVITY DATA
Incompatability (Materials to avoid): Strong oxidizing agents. Sparks & open flame
Hazardous Decomposition Products: On combustion CO, CO ₂ , Aldehydes and other organics, oxides of nitrogen. MAYOCCUR CONDITIONS TO AVOID On combustion CO, CO ₂ , Aldehydes and other organics, oxides of nitrogen. XXX WILL NOT OCCUR
Section VII — SPILL OR LEAK PROCEDURES
Prevent liquid from entering sewers, water sources, or low areas. Keep unnecessary personnel aw Shut off source, if possible to do so without hazard. Contain spilled liquid with sawdust, sand waste bisposal method
Consult disposal expert and ensure conformity with local regulations.
Section VIII — SPECIAL PROTECTION INFORMATION
RESPIRATORY PROTECTION: Use approved respiratory protection such as an air-supplied mask if used in non-ventilated area. Mechanical: Explosion-proof ventilation equipment. No smoking or open lights.
VENTILATION: Face velocity > 60 fpm in confined area
Protective Gloves: Chemically resistant gloves. EYEPROTECTION: Chemical splash goggles or face shield.

EQUIPMENT: Eye bath & Safety Shower.

Section IX - SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING: Keep containers closed when not in use. Do No handle or store near flame, heat or strong oxidants. Adequate ventilation required. Containers of this product may be hazardous when emptied - these containers retain product residues (vapor, liquid, et

'All handling equipment should be electrically grounded. Treat as a very flammable liquid.

Lee A. Dickinson Technical Service Manager